




AVX Corporation

CP0402A2350FLTR

Nimewo Pati:	CP0402A2350FLTR
Manifakti / Brand:	AVX Corporation
Pwodwi deskripsyon	RF DIR COUPLER 2.35GHZ 0402
Datasheets:	PDF CP0402A2350FLTR.pdf
RoHS Status	 Gen plon / RoHS ki pa konfòme
Bato de	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

[DEMANN POU SITASYON](#)

Imaj ka reprezantasyon. Gade espesifikasyon pou detay pwodwi.













Espesifikasyon nan CP0402A2350FLTR

NIMEWO PATI	CP0402A2350FLTR
MANIFAKTI	AVX Corporation
DESKRIPSYON	RF DIR COUPLER 2.35GHZ 0402
PLON GRATIS STATUS / ROHS STATUS	Gen plon / RoHS ki pa konfòme
DONE FÈY	PDF CP0402A2350FLTR.pdf
FOUNISÈ APARÈY PAKE	0402
SERI	-
RETOUNEN PÈT	-
POUVWA - MAX	3W
ANBALAJ	Tape & Reel (TR)
PAKE / KA	0402 (1005 Metric)
IMIDITE SANSIBLITE NIVO (MSL)	1 (Unlimited)
MANIFAKTI CREOLE TAN LEAD	10 Weeks
PLON GRATIS STATUS / ROHS STATUS	Contains lead / RoHS non-compliant
IZOLASYON	-
PERYONE ENPOZISYON	-
FREKANS	2.35GHz
DETAYE DESKRIPSYON	RF Directional Coupler 2.35GHz 3W 0402 (1005 Metric)
KOUPLE FAKTÈ	-
COUPLER TIP	Standard
APLIKASYON	-

Tags ki gen rapò

AVX Corporation CP0402A2350FLTR	Distribitè CP0402A2350FLTR	Founisè CP0402A2350FLTR
Pri CP0402A2350FLTR	CP0402A2350FLTR Foto	CP0402A2350FLTR Imaj
CP0402A2350FLTR PDF Datasheet	CP0402A2350FLTR Download Datasheet	Fèy CP0402A2350FLTR
CP0402A2350FLTR Stock	Achte CP0402A2350FLTR	Achte AVX Corporation CP0402A2350FLTR
AVX Corporation CP0402A2350FLTR	AVX Corporation Supplier	Distribitè AVX Corporation
AVX Corporation CP0402A2350FLTR	AVX Corporation [MIL] CP0402A2350FLTR	

Pwodwi ki gen rapò

 <p>CP0402A2442ALTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4-2.484GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A1960ALTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 1.93-1.99GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>
 <p>CP0402A2442FLTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4-2.484GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A2140ELTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.14GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>
 <p>CP0402A1960CNTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 1.93-1.99GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A2442ELTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4-2.484GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>
 <p>CP0402A2442FNTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4-2.484GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A1960ELTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 1.93-1.99GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>
 <p>CP0402A2400ELTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A1960DLTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 1.93-1.99GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>
 <p>CP0402A2400FLTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 2.4GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>	 <p>CP0402A1950FLTR Konpayi fabrikasyon: AVX Corporation Deskripsyon: RF DIR COUPLER 1.9GHZ 0402 Nan stok: Out stock</p> <p>RFQ</p>