



SICK

## DGS35-3HK04096

Nimewo Pati:	DGS35-3HK04096
Manifakti / Brand:	SICK
Pwodwi deskripsyon	ROTARY ENCODR INCREMENT 4096PPR
Datasheets:	
Bato de	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS


[DEMANN POU SITASYON](#)

Imaj ka reprezantasyon. Gade espesifikasyon pou detay pwodwi.













## Espesifikasyon nan DGS35-3HK04096

NIMEWO PATI	DGS35-3HK04096
MANIFAKTI	SICK
DESKRIPSYON	ROTARY ENCODR INCREMENT 4096PPR
PLON GRATIS STATUS / ROHS STATUS	
DONE FÈY	
VOLTAGE - PWOVIZYON POU	8 V ~ 24 V
STYLE REVOKASYON	Cable
SERI	-
LAVI WOTASYON (SIK MIN)	-
PULSASYON PA REVOLISYON	4096
KALITE SÒTI	-
LÒT NON YO	1070067
ORYANTASYON	User Selectable
MOUNTING KALITE	Chassis Mount
MANIFAKTI CREOLE TAN LEAD	3 Weeks
KALITE ENCODER	Incremental
DETÈMINE	No
BATI NAN CHANJMAN	No
KALITE ACTUATOR	Hole for Shaft

## Tags ki gen rapò

SICK DGS35-3HK04096	Distribitè DGS35-3HK04096	Founisè DGS35-3HK04096
Pri DGS35-3HK04096	DGS35-3HK04096 Foto	DGS35-3HK04096 Imaj
DGS35-3HK04096 PDF Datasheet	DGS35-3HK04096 Download Datasheet	Fèy DGS35-3HK04096
DGS35-3HK04096 Stock	Achte DGS35-3HK04096	Achte SICK DGS35-3HK04096
SICK DGS35-3HK04096	SICK Supplier	Distribitè SICK
SICK DGS35-3HK04096		

## Pwodwi ki gen rapò

 <p><b>DGS35-3HL02048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-3HK02500</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2500PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-3HN00360</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENTAL 360PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-3H204096</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 4096PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-2LK02048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-3HK02048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-3K402048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-3K401024</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 1024PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-3J408192</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 8192PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-2L404096</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 4096PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-3KK01024</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 1024PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-2LK16384</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 16384PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>