



SICK

## DGS35-1KK02048

Nimewo Pati:	DGS35-1KK02048
Manifakti / Brand:	SICK
Pwodwi deskripsyon	ROTARY ENCODR INCREMENT 2048PPR
Datasheets:	
Bato de	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS


[DEMANN POU SITASYON](#)

Imaj ka reprezantasyon. Gade espesifikasyon pou detay pwodwi.













## Espesifikasyon nan DGS35-1KK02048

NIMEWO PATI	DGS35-1KK02048
MANIFAKTI	SICK
DESKRIPSYON	ROTARY ENCODR INCREMENT 2048PPR
PLON GRATIS STATUS / ROHS STATUS	
DONE FÈY	
VOLTAGE - PWOVIZYON POU	4.5 V ~ 5.5 V
STYLE REVOKASYON	Cable
SERI	-
LAVI WOTASYON (SIK MIN)	-
PULSASYON PA REVOLISYON	2048
KALITE SÒTI	-
LÒT NON YO	1077268
ORYANTASYON	User Selectable
MOUNTING KALITE	Chassis Mount
MANIFAKTI CREOLE TAN LEAD	3 Weeks
KALITE ENCODER	Incremental
DETÈMINE	No
BATI NAN CHANJMAN	No
KALITE ACTUATOR	Hole for Shaft

## Tags ki gen rapò

SICK DGS35-1KK02048	Distribitè DGS35-1KK02048	Founisè DGS35-1KK02048
Pri DGS35-1KK02048	DGS35-1KK02048 Foto	DGS35-1KK02048 Imaj
DGS35-1KK02048 PDF Datasheet	DGS35-1KK02048 Download Datasheet	Fèy DGS35-1KK02048
DGS35-1KK02048 Stock	Achte DGS35-1KK02048	Achte SICK DGS35-1KK02048
SICK DGS35-1KK02048	SICK Supplier	Distribitè SICK
SICK DGS35-1KK02048		

## Pwodwi ki gen rapò

 <p><b>DGS35-1KK01024</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 1024PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1J405000</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 5000PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KN02048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1KK02500</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2500PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1JK04096</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 4096PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1J202048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1K200120</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENTAL 120PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1L202048</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2048PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1KK05000</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 5000PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1L202500</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 2500PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>
 <p><b>DGS35-1K405000</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 5000PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>	 <p><b>DGS35-1L204096</b> Konpayi fabrikasyon: SICK Deskripsyon: ROTARY ENCODR INCREMENT 4096PPR Nan stok: Out stock</p> <p><a href="#">RFQ</a></p>