


N/A

CDCV850DGGRG4

Nimewo Pati:	CDCV850DGGRG4
Manifakti / Brand:	N/A
Pwodwi deskripsyon	IC PLL CLOCK DRVR 2.5V 48TSSOP
Datasheets:	
RoHS Status	 Plon gratis / RoHS konfòme
Bato de	Hong Kong
Shipment Way	DHL/Fedex/TNT/UPS/EMS

[DEMANN POU SITASYON](#)

Imaj ka reprezantasyon. Gade espesifikasyon pou detay pwodwi.













Espesifikasyon nan CDCV850DGGRG4

NIMEWO PATI	CDCV850DGGRG4
MANIFAKTI	N/A
DESKRIPSYON	IC PLL CLOCK DRVR 2.5V 48TSSOP
PLON GRATIS STATUS / ROHS STATUS	Plon gratis / RoHS konfòme
DONE FÈY	
VOLTAGE - PWOVIZYON POU	2.3 V ~ 2.7 V
KALITE	PLL Clock Driver
FOUNISÈ APARÈY PAKE	48-TSSOP
SERI	-
PWOPÒSYON - ANTRE: SÒTI	1:11
ANBALAJ	Tape & Reel (TR)
PAKE / KA	48-TFSOP (0.240", 6.10mm Width)
PLL	Yes with Bypass
SÒTI	SSTL-2
OPERATING TANPERATI	0°C ~ 85°C
NIMEWO NAN SIKUI	1
MOUNTING KALITE	Surface Mount
IMIDITE SANSIBLITE NIVO (MSL)	2 (1 Year)
PLON GRATIS STATUS / ROHS STATUS	Lead free / RoHS Compliant
ANTRE	LVTTL, SSTL-2
FREKANS - MAX	140MHz
DIVIZYON / MILTIPLIKATÈ	No/No
DIFERANS - ANTRE: SÒTI	Yes/Yes
NIMEWO PATI BASE	CDCV850

Tags ki gen rapò

CDCV850DGGRG4	Distribitè CDCV850DGGRG4	Founisè CDCV850DGGRG4
Pri CDCV850DGGRG4	CDCV850DGGRG4 Foto	CDCV850DGGRG4 Imaj
CDCV850DGGRG4 PDF Datasheet	CDCV850DGGRG4 Download Datasheet	Fèy CDCV850DGGRG4
CDCV850DGGRG4 Stock	Achte CDCV850DGGRG4	Achte CDCV850DGGRG4
CDCV850DGGRG4	Supplier	Distribitè

Pwodwi ki gen rapò

 <p>CDCV850DGGR Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48-TSSOP Nan stok: 26517 pcs</p> <p>RFQ</p>	 <p>CDCV304TPWREP Konpayi fabrikasyon: N/A Deskripsyon: IC CLK BUFFER 1:4 200MHZ 8TSSOP Nan stok: 21714 pcs</p> <p>RFQ</p>
 <p>CDCV304PWR Konpayi fabrikasyon: N/A Deskripsyon: IC CLK BUFFER 1:4 200MHZ 8TSSOP Nan stok: 53713 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGG4 Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48TSSOP Nan stok: 14095 pcs</p> <p>RFQ</p>
 <p>CDCV850IDGG Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48-TSSOP Nan stok: 23791 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGR Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48TSSOP Nan stok: 4418 pcs</p> <p>RFQ</p>
 <p>CDCV850DGGG4 Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48TSSOP Nan stok: 19469 pcs</p> <p>RFQ</p>	 <p>CDCV850IDGGRG4 Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48TSSOP Nan stok: 4037 pcs</p> <p>RFQ</p>
 <p>CDCV304PWRG4 Konpayi fabrikasyon: N/A Deskripsyon: IC CLK BUFFER 1:4 200MHZ 8TSSOP Nan stok: 66794 pcs</p> <p>RFQ</p>	 <p>CDCV855IPW Konpayi fabrikasyon: N/A Deskripsyon: IC 1:4 DDR PLL CLK-DRVR 28-TSSOP Nan stok: 38134 pcs</p> <p>RFQ</p>
 <p>CDCV850DGG Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 48-TSSOP Nan stok: 22414 pcs</p> <p>RFQ</p>	 <p>CDCV855IPWG4 Konpayi fabrikasyon: N/A Deskripsyon: IC PLL CLOCK DRVR 2.5V 28TSSOP Nan stok: 26506 pcs</p> <p>RFQ</p>